

OPTIMUS 50/65/80 RAD-R/F (files available in PDF)

FCO-No.	Date	Class	Title	Size in KB	Distribution List
00135000	01.0	I	Index sheet	12	
74200002	Apr 2002	APR	Optimus RAD / RF release 3.x upgrade to release 3.5	54	
00135016	Jul 2001	SR	Error 00TH during tube adaptation	544	
00135015	Mar 2000	SR	Error combination 02WK + 02HG + 02HH + 00XO	253	
00135014	Jun 2000	AP	FW Update kV-Control Rel 3.2 OPTIMUS RAD, resp. Rel 1.2 OPTIMUS R/F	71	
00135012	Sep 2000	AP	X-Star tube and Rotor Control replacement	36	List
00135011	Sep 1999	AP	PCB EZ 102 low voltage supply exchange - <i>(only United Kingdom)</i>	40	
00135010	Apr 1999	AP	Einschaltstromdämpfung ROCO <i>(for Germany only)</i>	87	
00135009	May 1999	MA	Electric shock during service activities in the generator cabinet	75	direct
00135008	Jun 1999	AP	Replacement of OPTIMUS Rotor Control HS 9890 000 02211 - 4512 104 33791/2 - with plan of delivery	29	
00135007	Nov 1999	SR	ENK 2 contact problems	32	
00135006	Feb 2000	AP	Upgrade of release 3.x Optimus generators to release 3.3 Upgrade documentation rel. 3.3	107	direct
00135005	Jun 1998	AP	Upgrade of release 2.2 OPTIMUS generators to release 2.3 Upgrade documentation rel. 2.3	21 240	
00135004	May 1998	SR	Error combination 00X1 + 00M3	66	
00135003	Mar 1997	AP	Upgrade of OPTIMUS generators to release 2.2 - <i>(distributed directly)</i>	78	
00135002	Oct 1996	AP	Upgrade of OPTIMUS generators to release 2.2 - <i>(distributed directly)</i>	66	
00135001	Aug 1996	AP	Upgrade of OPTIMUS generators to release 2.2 - <i>(only USA)</i>	67	